


SERVICE PARTS LIST FOR MITSUBISHI ELECTRIC REFRIGERATION SYSTEMS:CHILLING UNIT

Series : ERCV-M900YA(KR)

Oct. 2023
BWE023370


INDEX
ERCV-M900YA ERCV-M900YAKR



ERCV-M900YA
ERCV-M900YAKR

EXTERNAL PARTS

[illegible]




*1 When replacing part 204 (Plate HEX assy), also replace part 222 (Insulator).


*2 When replacing part 216 (Thermistor <TH7>), also replace part 223 (Insulator).
 When replacing part 216 (Thermistor <TH9>), also replace part 223 (Insulator).

4


CONTROL BOX PARTS




Behind the plate inside the control box



Back of the control box



ELECTRIC BOX PARTS



[illegible]

mitsubishi **electric** **corporation**

BWE023370(20231031)